



INSPECTION DATE:

PREPARED BY:





Florida Building Inspection Group PO Box 1633 Riverview, FL 33568

(813) 409 3249

Fax: (813) 436-5260

flbigroup.com

Clientcare@FLBIgroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

Priority Maintenance Items


## Exterior


SITE INFO

## **RECOMMENDATIONS \ Overview**

REFERENCE

Condition: • Exterior Punch List






1. Paint touchups



2. Paint touchups



3. Loose stone work

4. Paint touchups

SUMMARY Report No. 21885


SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE





7. Missing fasteners



6. Caulking needed



8. Paint touchups

COOLING INSULATION SUMMARY ROOFING EXTERIOR STRUCTURE HEATING PLUMBING INTERIOR SITE INFO REFERENCE



9. Exposed drywall screws



10. Does not open fully



11. Adjustment needed to stucco at threshold



12. Adjustment needed to stucco at threshold

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE



13. Caulking needed behind kickout



14. Light noted around garage door



15. Adjustment needed to garage door



16. Adjustment needed to garage door

flbigroup.com


SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE



17. Sealant needed

**SUMMARY** 



18. Minor damage to drywall



19. Paint touchups


20. Exterior Punch List

SUMMARY Report No. 21885


SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE





21. Paint drips



22. Caulking needed




23. Sealant needed

24. Paint touchups

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR
SITE INFO REFERENCE




25. Sealant needed

## Interior

## **RECOMMENDATIONS \ Overview**

Condition: • Interior Punch List

Majority of items noted are either Paint (blue tape) or Drywall (green tape) touchups or repairs unless specifically noted.



26. Seam in carpet



27. Interior Punch List

HEATING

flbigroup.com

COOLING

SITE INFO REFERENCE

ROOFING

SUMMARY



EXTERIOR

STRUCTURE

28. Inoperative lights



30. Interior Punch List



INSULATION

PLUMBING

INTERIOR

29. Interior Punch List



31. Interior Punch List

PLUMBING

INTERIOR

**SUMMARY** flbigroup.com

HEATING

COOLING

SITE INFO REFERENCE

ROOFING

SUMMARY



EXTERIOR

STRUCTURE

32. Sealant needed around plenum on inside



INSULATION

33. Sealant needed around plenum on inside



34. Sealant needed around plenum on inside




35. Conduit needed - must be complete to wall

SUMMARY Report No. 21885

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE






36. Seam in carpet



37. Exposed finish nails on trim



38. Interior Punch List

39. Noisy hinge

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE



40. Stiff/adjustment needed



41. Interior Punch List



42. Interior Punch List



43. Interior Punch List

SUMMARY Report No. 21885

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE



44. Interior Punch List



45. Grout cracking



46. Missing grout



47. Interior Punch List

SUMMARY Report No. 21885


flbigroup.com

HEATING

SITE INFO REFERENCE

ROOFING

SUMMARY



EXTERIOR

STRUCTURE

48. Interior Punch List




COOLING

INSULATION

PLUMBING

INTERIOR



50. Cracked door



51. Interior Punch List

**SUMMARY** flbigroup.com COOLING INSULATION SUMMARY ROOFING EXTERIOR STRUCTURE HEATING PLUMBING INTERIOR

SITE INFO REFERENCE




52. Interior Punch List



53. Interior Punch List



54. No power to outlet



55. Stiff/adjustment needed

SUMMARY Report No. 21885

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE





56. Interior Punch List






58. Loose outlet

59. Grout touchups

flbigroup.com COOLING INSULATION SUMMARY ROOFING EXTERIOR STRUCTURE HEATING PLUMBING INTERIOR

SITE INFO REFERENCE

**SUMMARY** 



60. Grout touchups



61. Adjustment needed



62. Adjustment needed



63. Scratch

Report No. 21885


**SUMMARY** flbigroup.com

COOLING INSULATION SUMMARY ROOFING EXTERIOR STRUCTURE HEATING PLUMBING INTERIOR SITE INFO REFERENCE






64. Interior Punch List



65. Minor damage



66. Interior Punch List

67. Interior Punch List

SUMMARY Report No. 21885

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE





68. Interior Punch List

69. Stiff/adjustment needed



70. Missing bulb

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

Home Improvement - ballpark costs

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERE

## Description

## Sloped roofing material:

Asphalt shingles




71. Asphalt shingles



73. Asphalt shingles



72. Asphalt shingles



74. Asphalt shingles

ROOFING Report No. 21885

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCI





75. Asphalt shingles

76. Asphalt shingles



77. Asphalt shingles

Sloped roof flashing material: • Metal

Probability of leakage: • Low

Approximate age: • New

Typical life expectancy: • 20-25 years

ROOFING Report No. 21885

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

## Limitations

### Roof inspection limited/prevented by:

- · Lack of access (too high/steep)
- Lack of access (too slippery/fragile)

Walking on new roofs could cause damage and void manufacturer and/or builder warranty

Inspection performed: • With a drone

Age determined by: • Real estate listing

# Recommendations

### **RECOMMENDATIONS \ Overview**

1. Condition: • No roofing recommendations are offered as a result of this inspection.

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCI

# Description

### General:

· General exterior



78. General exterior



80. General exterior



79. General exterior



81. General exterior

Report No. 21885

**EXTERIOR** flbigroup.com

SUMMARY ROOFING **EXTERIOR** STRUCTURE INSULATION INTERIOR



82. General exterior

Gutter & downspout material: • No gutters or downspouts

Lot slope: • Away from building

Soffit (underside of eaves) and fascia (front edge of eaves): • Aluminum

Wall surfaces and trim: • Stucco • Fiber cement siding

Driveway: • Concrete • No performance issues were noted.

Walkway: • Concrete • No performance issues were noted.

Garage: • Attached

Garage vehicle doors: • Present

Garage vehicle door operator (opener): • Present

Irrigation/Lawn sprinklers:

Automatic







flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENC





85. Automatic 86. Automatic


## Limitations

**Upper floors inspected from:** • Ground level **Exterior inspected from:** • Ground level


## Recommendations

### **RECOMMENDATIONS \ Overview**

2. Condition: • Exterior Punch List



87. Paint touchups



88. Paint touchups

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE



89. Loose stone work



90. Paint touchups



91. Seal hole



92. Caulking needed

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE



93. Missing fasteners



94. Paint touchups



95. Exposed drywall screws



96. Does not open fully

flbigroup.com


SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR



97. Adjustment needed to stucco at threshold



98. Adjustment needed to stucco at threshold



99. Caulking needed behind kickout



100. Light noted around garage door

flbigroup.com


SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR



101. Adjustment needed to garage door



102. Adjustment needed to garage door



103. Sealant needed



104. Minor damage to drywall

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR






105. Paint touchups



106. Exterior Punch List



107. Paint drips

108. Caulking needed

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR


SITE INFO REFERENCE





109. Sealant needed

110. Paint touchups



111. Sealant needed

### IRRIGATION/SPRINKLER SYSTEM \ Observations

3. Condition: • Irrigation system was tested & was operating properly at time of inspection. Minor adjustments to sprinkler heads may be required.

STRUCTURE Report No. 21885

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

## Description

Configuration: • Slab-on-grade

Foundation material: • Poured concrete

Floor construction:

Joists

Second floor

Concrete

First floor

#### **Exterior wall construction:**

Wood frame

Second floor

Masonry

First floor

Roof and ceiling framing: • Trusses • Oriented Strand Board (OSB) sheathing

## Limitations

Inspection limited/prevented by: • Ceiling, wall and floor coverings • Carpet/furnishings

#### Attic/roof space:

Inspected from access hatch

Walking through new insulation could cause damage and void manufacturer and/or builder warranty

Not included as part of a building inspection: • Visible mold evaluation is not included in the building inspection report

### Recommendations

#### **RECOMMENDATIONS \ Overview**

4. Condition: • No structure recommendations are offered as a result of this inspection.

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENC

## Description

Service entrance cable and location: • Underground - cable material not visible

Service size: • 200 Amps (240 Volts)

Main disconnect/service box rating: • 200 Amps Main disconnect/service box type and location:

• Breakers - exterior wall



112. Breakers - exterior wall



113. Breakers - exterior wall

System grounding material and type: • Copper - Ufer

Distribution panel type and location:

• Breakers - garage



114. Breakers - garage



115. Breakers - garage

ELECTRICAL Report No. 21885

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

**Distribution panel rating:** • Not determined **Electrical panel manufacturers:** • Square D

Number of circuits installed: • 18

Distribution wire (conductor) material and type: • Copper - non-metallic sheathed

Type and number of outlets (receptacles): • Grounded - typical

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • GFCI - kitchen • GFCI - garage • GFCI - bathroom

and exterior • GFCI - panel • AFCI - panel

Smoke alarms (detectors): • Present

Carbon monoxide (CO) alarms (detectors): • Combination smoke/CO alarm(s) noted

## Limitations

#### Panel covers:

Disconnect covers are not removed by the building inspector
 Removing panel cover could cause damage and void manufacturer and/or builder warranty

System ground: • Quality of ground not determined

Circuit labels: • The accuracy of the circuit index (labels) was not verified.

Not included as part of a building inspection: • Low voltage wiring systems and components

#### Recommendations

#### **RECOMMENDATIONS \ Overview**

5. Condition: • No electrical recommendations are offered as a result of this inspection.

HEATING Report No. 21885

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

## Description

System type: • Heat pump

Fuel/energy source: • Electricity

Heat pump manufacturer:

Carrier





117. Carrier

116. Carrier

Heat distribution: • Ducts and registers

Approximate capacity: • 5 kW

Efficiency: • Conventional
Approximate age: • New

Typical life expectancy: • Heat Pump 12 to 15 years

Failure probability: • Low

## Limitations

Safety devices: • Not tested as part of a building inspection

Warm weather: • Prevents testing heating effectiveness • Prevented testing in heating mode

Heat loss calculations: • Not done as part of a building inspection

Heat exchanger: • Not visible • Not accessible

HEATING Report No. 21885

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

## Recommendations

## **RECOMMENDATIONS \ Overview**

6. Condition: • No heating recommendations are offered as a result of this inspection.

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

# Description

Air conditioning type: • Air cooled

Heat pump type: • Air source

Manufacturer:

Carrier





119. Carrier

118. Carrier

Cooling capacity: • 3 Tons
Compressor type: • Electric

Compressor approximate age: • New Typical life expectancy: • 12 to15 years

Failure probability: • Low

Supply temperature:

• 43°

## **COOLING & HEAT PUMP**

flbigroup.com SUMMARY STRUCTURE ELECTRICAL PLUMBING ROOFING EXTERIOR COOLING INTERIOR



120. 43°

Return temperature: • 58°



121. 58°

Temperature difference across cooling coil: • 15° • Acceptable temperature difference: 14° to 22° • This suggests good performance.

Evaporative cooler damper location: • Rear of building

Refrigerant type: • R-410A

Condensate system: · Discharges to exterior SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE



122. Discharges to exterior

· Automatic shut-off device in place



123. Automatic shut-off device in place

# Limitations

**Inspection limited/prevented by:** • Heat pumps are not operated in the heating mode when the outdoor temperature is above 70°F

Heat pump only tested in: • Cooling mode

Heat gain calculations: • Not done as part of a building inspection

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

## Recommendations

### **RECOMMENDATIONS \ Overview**

7. Condition: • No air conditioning or heat pump recommendations are offered as a result of this inspection.

# **INSULATION AND VENTILATION**

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

# Description

### Attic/roof insulation material:

· Glass fiber






124. Glass fiber 125. Glass fiber

#### Attic/roof insulation amount/value:

• R-38



126. R-38

Attic/roof ventilation: • Roof and soffit vents

Wall insulation material: • Not visible

Wall insulation amount/value: • Not visible

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

## Limitations

### Attic inspection performed:

From access hatch

Walking through new insulation could cause damage and void manufacturer and/or builder warranty

### Recommendations

#### **RECOMMENDATIONS \ Overview**

8. Condition: • No insulation recommendations are offered as a result of this inspection.

Report No. 21885 **PLUMBING** 

flbigroup.com

INSULATION SUMMARY EXTERIOR STRUCTURE **PLUMBING** INTERIOR

SITE INFO

# Description

Water supply source (based on observed evidence): • Public

Service piping into building: • Plastic

Supply piping in building: • CPVC (Chlorinated PolyVinylChloride)

Main water shut off valve at the:

Exterior wall



127. Exterior wall

Meter





129. Meter



130. Meter

### Water flow and pressure:

• Typical for neighborhood

PLUMBING Report No. 21885

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR



131. Typical for neighborhood

Water heater type: • Conventional Water heater location: • Garage

Water heater fuel/energy source: • Electric

Water heater manufacturer:

· A.O. Smith



132. A.O. Smith 133. A.O. Smith

Water heater tank capacity: • 50 gallons Water heater approximate age: • New

Water heater typical life expectancy: • 8 to 12 years

Water heater failure probability: • Low

ELECTRIC STORAGE TANK WATER HEATER

MAKKAKAN

PLUMBING Report No. 21885

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

### Hot water temperature (Generally accepted safe temp. is 120° F):

• 105° F



134. 105° F

Waste disposal system: • Public

Waste and vent piping in building: • PVC plastic Exterior hose bibb (outdoor faucet): • Present

### Limitations

Items excluded from a building inspection: • Water quality • Isolating/relief valves & main shut-off valve • Concealed plumbing • Tub/sink overflows • Water treatment equipment • Water heater relief valves are not tested • Water lines and ice makers

#### Not included as part of a building inspection:

· Washing machine connections

Washing machine supply valves are not tested when no washing machine is present

### Recommendations

#### **RECOMMENDATIONS \ Overview**

9. Condition: • No plumbing recommendations are offered as a result of this inspection.

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

Description

Major floor finishes: • Carpet • Tile

Major wall finishes: • Plaster/drywall

Major ceiling finishes: • Plaster/drywall

Major wall and ceiling finishes: • Plaster/drywall

Windows:
• Inspected

All windows accessible at the time of inspection were tested and operating normally unless otherwise noted in this report.

· Single/double hung

Glazing: • Double

Exterior doors - type/material: • Vinyl-clad • Sliding glass • Solid wood • Garage door - metal

Doors:

Inspected

All interior and exterior doors accessible at the time of inspection were tested and operating normally unless otherwise noted in this report.

Oven type: • Conventional
Oven fuel: • Electricity

Range fuel: • Electricity

Appliances:
Range





135. Range 136. Range

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR



137. Range

Dishwasher



138. Dishwasher

Waste disposal

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR



139. Waste disposal

- Door bell
- Microwave/Exhaust Fan Combo



140. Microwave/Exhaust Fan Combo



141. Microwave/Exhaust Fan Combo

Laundry facilities: • Hot/cold water supply • Vented to outside • 120-Volt outlet • 240-Volt outlet • Waste standpipe

Kitchen ventilation: • Recirculating type

**Bathroom ventilation:** • Exhaust fan • Operable window **Laundry room ventilation:** • Clothes dryer vented to exterior

Counters and cabinets: • Inspected
Stairs and railings: • Inspected

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

### Limitations

Not included as part of a building inspection: • Carbon monoxide alarms (detectors), security systems, central vacuum

**Appliances:** • Appliances are not moved during an inspection • All appliances present at the time of inspection were tested and operating normally unless otherwise noted in this report

Garage door: • Tested


Garage door opener: • Tested

### Recommendations

#### **RECOMMENDATIONS \ Overview**

10. Condition: • Interior Punch List

Majority of items noted are either Paint (blue tape) or Drywall (green tape) touchups or repairs unless specifically noted.



142. Seam in carpet



144. Inoperative lights



143. Interior Punch List



145. Interior Punch List


flbigroup.com



146. Interior Punch List



148. Sealant needed around plenum on inside



147. Interior Punch List




149. Sealant needed around plenum on inside

flbigroup.com



150. Sealant needed around plenum on inside








152. Seam in carpet


153. Exposed finish nails on trim

flbigroup.com





154. Interior Punch List



155. Noisy hinge



156. Stiff/adjustment needed

157. Interior Punch List

flbigroup.com





158. Interior Punch List



159. Interior Punch List



160. Interior Punch List

161. Grout cracking

flbigroup.com






162. Missing grout




163. Interior Punch List



164. Interior Punch List

165. Interior Punch List

flbigroup.com





166. Cracked door



167. Interior Punch List




168. Interior Punch List

169. Interior Punch List

flbigroup.com



170. No power to outlet



171. Stiff/adjustment needed




172. Interior Punch List




173. Interior Punch List

flbigroup.com






174. Loose outlet



175. Grout touchups



176. Grout touchups

177. Adjustment needed

flbigroup.com



178. Adjustment needed



179. Scratch





180. Interior Punch List




181. Minor damage

flbigroup.com





182. Interior Punch List



183. Interior Punch List



184. Interior Punch List

185. Stiff/adjustment needed



186. Missing bulb

SITE INFO Report No. 21885

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

## Description

Weather: • Sunny

Attendees: • Contractor

Occupancy: • The home was vacant during the inspection.

**Utilities:** • All utilities were on during the inspection.

Approximate age of home: • New

Approximate date of construction: • 2021

Building type: • Detached home

Number of stories: • 2

**END OF REPORT** 

## REFERENCE LIBRARY

flbigroup.com

SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

SITE INFO REFERENCE

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

- 01. ROOFING, FLASHINGS AND CHIMNEYS
- 02 EXTERIOR
- 03. STRUCTURE
- 04. ELECTRICAL
- 05. HEATING
- 06. COOLING/HEAT PUMPS
- 07. INSULATION
- 08. PLUMBING
- 09. INTERIOR
- 10. APPLIANCES
- 11. LIFE CYCLES AND COSTS
- 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

- 13. HOME SET-UP AND MAINTENANCE
- 14. MORE ABOUT HOME INSPECTIONS