

a few days, then was stored in my garage for more than two years. Sadly, Paul passed away in October of 2010. In the following summer, Cathy and I began the restoration.




Figure 1 : Damage to fiberglass and keel.




Figure 2 : Damage to bow fiberglass.

(2) Cathy and I stripped all of the fiber glass from the bottom of the boat (see attendant photographs). In most places, the fiber glass was split, cracked, and/or fractured from being banged against rocks and other marine